

Date: Wednesday, 12/07/2006 3:41:46 PM  
 User: Linda Lacelle

## Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: RIGHT ARM WELDMENT
Job Number	: 27883		
Estimate Number	: 12104		
P.O. Number	: N/A	Part Number	: D3354043
This Issue	: 12/07/2006 S.O. No. : N/A	Drawing Number	: D3354 REV.A
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: N/A Type : LARGE FAB ASSY	Drawing Revision	: A
Previous Run	: N/A	Material	: N/A
Written By	: _____	Due Date	: 19/07/2006 Qty: 8 Um: Each
Checked & Approved By	: _____		
Comment	: est rev . A 06.01.25 new issue EC		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :								
1.0	D33543	shaft								
 										
Comment: Qty.: 1.0000 Each(s)/Unit Total : 8.0000 Each(s) pick: <table border="1"> <thead> <tr> <th>qty</th> <th>part number</th> <th>description</th> <th>batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>D3354-3</td> <td>shaft</td> <td>327658</td> </tr> </tbody> </table> CPC 06.07.12			qty	part number	description	batch	1	D3354-3	shaft	327658
qty	part number	description	batch							
1	D3354-3	shaft	327658							
2.0	D33545	right arm								
 										
Comment: Qty.: 1.0000 Each(s)/Unit Total : 8.0000 Each(s) pick: <table border="1"> <thead> <tr> <th>qty</th> <th>part number</th> <th>description</th> <th>batch</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>D3354-5</td> <td>right arm</td> <td>327657</td> </tr> </tbody> </table> CPC 06.07.12			qty	part number	description	batch	1	D3354-5	right arm	327657
qty	part number	description	batch							
1	D3354-5	right arm	327657							
3.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1								
 										
Comment: LARGE FABRICATION RESOURCE 1 1- Weld assembly as per dwg D3354  2-Grind welds flush as per dwg D3354 CPC 06.07.13										
4.0	QC5/9	WELD INSPECTION								
 										
Comment: WELD INSPECTION PD 06.07.18										

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Design Mgr	Approval QC Inspector
			Initial Design Mgr	Action Description Design Mgr	Sign & Date			

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☒ No ☐ DQA: ☒ \_\_\_\_\_ Date: 06/08/07

NOTE: Date & initial all entries

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

Date: Wednesday, 12/07/2006 3:41:46 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: RIGHT ARM WELDMENT

Job Number: 27883

Part Number: D3354043

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

1-Mask areas indicated on dwg D3354

2-Powder Coat Fire Red (Ref: 4.3.5.10) as per QSI 005 4.3

*DL 06/08/16 (8)*

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

*DL 6/8/21 (8)*

7.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: 351

*DL 6/8/21 (8)*

8.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

*DL 06.08.22*

Job Completion



*CL 06/08/21*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Design Mgr	Approval QC Inspector
			Initial Design Mgr	Action Description Design Mgr	Sign & Date			

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

NOTE: Date & initial all entries

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_